

Inspection Photos

Operator: Logos Operating

API: 05-067-05775

Date: 10/30/2018



Photo 1. View of project area from the northern corner facing center. Revegetation is progressing with intermediate wheatgrass (*Thinopyron intermedium*), sand dropseed (*Sporobolus cryptandrus*), and big sagebrush (*Artemisia tridentata*).



Photo 2. View of the western project area from the northern corner facing southward.



Photo 3. View of the northeastern edge of the project area from the northern corner facing eastward.



Photo 3. View of musk thistles (*Carduus nutans*) within the interim reclamation area. Approximately 150 individuals observed.