

Inspection Photos

Operator: Logos Operating

API: 05-067-09136

Date: 10/30/2018



Photo 1. View of project area from the southeastern corner facing center. Revegetation is progressing with crested wheatgrass (*Agropyron cristatum*), sand dropseed (*Sporobolus cryptandrus*), and rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of the western portion of the project area from the southwestern corner facing northward.



Photo 4. View of rig anchor an marker (broken) within the working area.