

MARALEX RESOURCES, INC.– 53255

API # 05-077-08556 CAMP GULCH UNIT-FEDERAL #3-22-8-103

Inspection Date : 11/7/2018



Wellhead with separators , tank and blowdown pit in background



Separator with sign , blowdown pit, tank. Junk pipe, hose and valves. Unmarked NW anchor

MARALEX RESOURCES, INC.– 53255

API # 05-077-08556 CAMP GULCH UNIT-FEDERAL #3-22-8-103

Inspection Date : 11/7/2018



Overview of location from NW corner
looking SE



Unused separator

MARALEX RESOURCES, INC.– 53255

API # 05-077-08556 CAMP GULCH UNIT-FEDERAL #3-22-8-103

Inspection Date : 11/7/2018



**Meter housing and SW corner anchor
with marker**



Unmarked SE corner anchor