

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2018

Submitted Date:

11/05/2018

Document Number:

689702017**FIELD INSPECTION FORM**

Loc ID 435806	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: <u>22</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435798	WELL	PR	03/20/2014	GW	045-22297	NOLTE 44B-14	PR
435799	WELL	PR	07/09/2014	GW	045-22298	NOLTE 13B-13	PR
435800	WELL	PR	03/11/2014	GW	045-22299	NOLTE 11B-24	PR
435801	WELL	PR	04/08/2014	GW	045-22300	NOLTE 14C-13	PR
435802	WELL	PR	07/18/2014	GW	045-22301	NOLTE 44A-14	PR
435803	WELL	PR	06/29/2014	GW	045-22302	NOLTE 43C-14	PR
435804	WELL	PR	03/23/2014	GW	045-22303	NOLTE 11A-24	PR
435805	WELL	PR	09/17/2014	GW	045-22304	NOLTE 14D-13	PR
435807	WELL	PR	07/21/2014	GW	045-22305	NOLTE 13D-13	PR
435808	WELL	PR	03/15/2014	GW	045-22306	NOLTE 44C-14	PR
435809	WELL	PR	05/08/2014	GW	045-22307	NOLTE 13C-13	PR
435810	WELL	PR	07/05/2014	GW	045-22308	NOLTE 13A-13	PR
435811	WELL	PR	07/12/2014	GW	045-22309	NOLTE 43B-14	PR
435812	WELL	PR	04/24/2014	GW	045-22310	NOLTE 14A-13	PR
435813	WELL	PR	04/12/2014	GW	045-22311	NOLTE 14B-13	PR
435814	WELL	PR	07/11/2014	GW	045-22312	NOLTE 43A-14	PR
435989	WELL	PR	03/04/2014	GW	045-22325	NOLTE 11C-24	PR

General Comment:

Routine FIU General Field Inspection



Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	3 tanks in battery has labels in disrepair. Tank at pump house no label posted.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/06/2019
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	866-580-9382		
Corrective Action:		Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds around perimeter berms and in storm water bmps.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/16/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			

Inspected Facilities									
Facility ID:	435798	Type:	WELL	API Number:	045-22297	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435799	Type:	WELL	API Number:	045-22298	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435800	Type:	WELL	API Number:	045-22299	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435801	Type:	WELL	API Number:	045-22300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435802	Type:	WELL	API Number:	045-22301	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435803	Type:	WELL	API Number:	045-22302	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435804	Type:	WELL	API Number:	045-22303	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435805	Type:	WELL	API Number:	045-22304	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	435807	Type:	WELL	API Number:	045-22305	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435808	Type:	WELL	API Number:	045-22306	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435809	Type:	WELL	API Number:	045-22307	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435810	Type:	WELL	API Number:	045-22308	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435811	Type:	WELL	API Number:	045-22309	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435812	Type:	WELL	API Number:	045-22310	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435813	Type:	WELL	API Number:	045-22311	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	435814	Type:	WELL	API Number:	045-22312	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	435989	Type:	WELL	API Number:	045-22325	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
Check Dams	Pass					
		Gravel	Pass			
Compaction	Pass					
Berms	Pass					
				Material Handling And Spill Prevention		
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689702018	Inspection 689702017 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638644