

# Final Reclamation Inspection

November 6, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-001-09196

Inspection Document #: 682404159

Adams County, CO

NENE Section 1 T1S R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HSR-EPPINGER #1-1  
API: 05-001-09196



**Photo 1.** Photo taken from the entrance of the location, facing Southwest. Operator completed the previous corrective action to perform additional reclamation activities. Operator shall control weeds and erosion until the Location meets Rule 1004 standards. Note: Vehicle traffic was observed within final reclamation areas. Operator shall comply with Rule 1004 standards.

Inspection Photos  
Location Name: HSR-EPPINGER #1-1  
API: 05-001-09196



**Photo 2.** Photo taken along a portion of the access road, facing Southwest. See comments under Photo 1.

Inspection Photos  
Location Name: HSR-EPPINGER #1-1  
API: 05-001-09196



**Photo 3.** Photo taken from the northern well location, facing Southwest. See comments under Photo 1.