

HALLIBURTON

iCem[®] Service

EXTRACTION OIL & GAS-EBUS

For: Extraction

Rinn Valley East N17-20-3N Production

Job Date: Tuesday, August 28, 2018

Sincerely,

Ryan Keeran

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	7
2.1	Job Event Log	7
3.0	Job Charts.....	9
3.1	Job Chart.....	9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Rinn Valley East N17-20-3N** cement production casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 39 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 369404	Ship To #: 3892499	Quote #:	Sales Order #: 0905093710
Customer: EXTRACTION OIL & GAS		Customer Rep: Manuel Parres	
Well Name: RINN VALLEY EAST		Well #: N17-20-3N	API/UWI #: 05-123-47318-00
Field: WATTENBERG	City (SAP): FIRESTONE	County/Parish: WELD	State: COLORADO
Legal Description: SW SE-17-2N-68W-898FSL-1771FEL			
Contractor:		Rig/Platform Name/Num: Patterson 901	
Job BOM: 7523 7523			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA/HX38199		Srvc Supervisor: Kendall Broom - H194727	

Job

Formation Name	
Formation Depth (MD)	Top Bottom
Form Type	BHST
Job depth MD	17437ft Job Depth TVD
Water Depth	Wk Ht Above Floor
Perforation Depth (MD)	From To

Well Data

Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing	0	9.625	8.921	36		J-55	0	1622	0	
Casing	0	5.5	4.778	20	BTC	P-110	0	17427	0	
Open Hole Section			8.5				1665	17437		

Tools and Accessories

Type	Size in	Qty	Make	Depth ft	Type	Size in	Qty	Make
Guide Shoe	5.5				Top Plug	5.5		HES
Float Shoe	5.5			17437	Bottom Plug	5.5		HES
Float Collar	5.5				SSR plug set	5.5		HES
Insert Float	5.5				Plug Container	5.5	1	HES
Stage Tool	5.5				Centralizers	5.5		HES

Fluid Data

Stage/Plug #: 1

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	11.5 lb/gal Tuned Spacer III	Tuned Spacer III	50	bbl	11.5	3.73		6	
0.50 gal/bbl		MUSOL(R) A, 5 GAL PAIL (100064220)							
149.34 lbm/bbl		BARITE, BULK (100003681)							

35 gal/bbl		FRESH WATER							
0.50 gal/bbl		DUAL SPACER SURFACTANT B, 5 GAL PAIL (100003665)							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	ElastiCem	ELASTICEM (TM) SYSTEM	2725	sack	13.2	1.57		8	7.53
0.45 %		SCR-100 (100003749)							
7.53 Gal		FRESH WATER							
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Displacement	Displacement	386	bbl	8.33				
Cement Left In Pipe	Amount				Reason	Shoe Joint			
Mix Water:	pH 7	Mix Water Chloride:	0 ppm	Mix Water Temperature:	72°F °C				
Plug Bumped?	Yes				Floats Held?	Yes			
Cement Returns:	39 bbl								
Comment Got 39 bbl cement back to surface. Burst the shoe and pumped a 5 bbl wet shoe. Checked floats and got 3 bbl back. Floats held.									

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	Comb Pump Rate <i>(bbl/min)</i>	DH Density <i>(ppg)</i>	DS Pump Press <i>(psi)</i>	Comments
Event	1	Call Out	Call Out	8/28/2018	06:00:00	USER				Called crew out to be on location at 1200
Event	2	Depart Shop for Location	Depart Shop for Location	8/28/2018	10:00:00	USER				Held a safety meeting before leaving for location
Event	3	Arrive At Loc	Arrive At Loc	8/28/2018	11:00:00	USER				Arrive at location and met with the company man
Event	4	Rig-up Lines	Rig-up Lines	8/28/2018	11:30:00	USER				Held a hazard hunt before spotting in trucks and rigging up
Event	5	Safety Meeting	Safety Meeting	8/28/2018	15:30:00	USER	0.00	8.21	-30.00	Held a safety meeting with the rig to discuss the operation and safety
Event	6	Start Job	Start Job	8/28/2018	16:14:58	COM5	0.00	8.29	-13.00	Filled lines with 2 bbls water
Event	7	Test Lines	Test Lines	8/28/2018	16:16:45	COM5	0.00	7.90	141.00	Test lines to 4700 psi, with a 500 psi kick out, and the 5th gear stall.
Event	8	Pump Spacer 1	Pump Spacer 1	8/28/2018	16:25:25	COM5	0.00	8.04	30.00	Pumped 50 bbls Tuned Spacer, 11.5#, 3.73 yield, 23.4 gal/sks. Pumped at 4 bpm and 290 psi. Musol and surfactant were added on the fly.
Event	9	Pump Cement	Pump Cement	8/28/2018	16:38:20	COM5	6.00	12.37	489.00	Pumped 761 bbls Elasticem. 2725 sks, 13.2#, 1.57 yields, 7.53 gal/sks. Pumped at 8 bpm and 574 psi.

Event	10	Check Weight	Check Weight	8/28/2018	16:40:06	COM5	6.00	13.21	494.00	Verified weight with the pressurized scale
Event	11	Check Weight	Check Weight	8/28/2018	16:58:29	COM5	7.10	13.29	513.00	Verified weight with the pressurized scale
Event	12	Check Weight	Check Weight	8/28/2018	17:11:59	COM5	8.00	13.16	586.00	Verified weight with the pressurized scales
Event	13	Check Weight	Check Weight	8/28/2018	17:47:16	COM5	8.10	13.18	597.00	Verified weight with the pressurized scale
Event	14	Check Weight	Check Weight	8/28/2018	18:08:11	COM5	6.50	13.21	467.00	Verified weight with the pressurized scale
Event	15	Start Job	Start Job	8/28/2018	18:15:20	COM5	0.00	15.77	-41.00	Hit the flecs button to shut it off.
Event	16	Check Weight	Check Weight	8/28/2018	18:19:33	COM5	5.60	13.14	201.00	Verified weight with the pressurized scale
Event	17	Shutdown	Shutdown	8/28/2018	18:32:00	COM5	0.00	13.63	61.00	
Event	18	Drop Top Plug	Drop Top Plug	8/28/2018	18:34:59	COM5	0.90	13.51	-31.00	KLX dropped the plug witnessed by the company man
Event	19	Pump Displacement	Pump Displacement	8/28/2018	18:35:02	COM5	0.90	13.34	-24.00	Pumped 386 bbls water displacement. Pumped at 10-4 bpm. Got 39 bbls cement back to surface.
Event	20	Bump Plug	Bump Plug	8/28/2018	19:28:05	COM5	0.00	8.68	2455.00	Bumped the plug and kicked out at 2748 psi. Pressured up the well and burst the shoe at 3605 psi. Pumped 5 bbl wet shoe.
Event	21	End Job	End Job	8/28/2018	19:35:14	COM5	0.00	0.47	-21.00	
Event	22	Rig Down Lines	Rig Down Lines	8/28/2018	19:45:00	USER	1.90	8.11	-2.00	Held a safety meeting before rigging down lines
Event	23	Depart Location	Depart Location	8/28/2018	21:00:00	USER				Held a safety huddle before leaving location

3.0 Job Charts

3.1 Job Chart

