

**Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302327**



Location Photo #1



Location Photo #2

**Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302327**



Location Photo #3, unused equipment removed.



Location Photo #4, secondary liner repaired.

**Inspection Photo
Pitman 13-3A
API # 045-09551
Inspection # 689302327**



Location Photo #5, Secondary liner repaired