

Inspection Photos
Location Name: CLEMENTINE B COBURN B UNIT 1
Location ID: 318481




PHOTO 1: WELLHEAD



PHOTO 2: TANK BATTERY

Inspection Photos
Location Name: CLEMENTINE B COBURN B UNIT 1
Location ID: 318481



Colorado Oil & Gas Conservation Commission
40.11209, -104.80078, 217°
2018/11/07 14:02:05



Colorado Oil & Gas Conservation Commission
40.11176, -104.78446, 1485.0m, 182°
2018/11/07 14:08:23

PHOTO 3: There are 6 unmarked unused risers between meter house and heated separator

PHOTO 4: Lid to tank is removed and tank does not have any bird protection.