

Inspection Photos

Location Name: CLEMENTINE B COBURN B UNIT #1

Location ID: 318649



PHOTO 1: WELLHEAD

PHOTO 2: wellhead wet with fluid/ stained soil around wellhead

