



**Photo#1:**  
Overview of Location to Northeast.

October 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#335963





Photo#2:  
Overview of Location to Southwest.

October 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#335963





Photo#3:  
View of stabilized fill slope & robust vegetation..

October 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Loc#335963