

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2018

Submitted Date:

11/09/2018

Document Number:

692400315**FIELD INSPECTION FORM**

Loc ID 335963	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 2 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																											
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																																																															
Contact Information: <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>cogcc.inspections@caerusoilandgas.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment			cogcc.inspections@caerusoilandgas.com		ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE																																																																																																																			
Contact Name	Phone	Email	Comment																																																																																																																												
		cogcc.inspections@caerusoilandgas.com																																																																																																																													
Inspected Facilities: <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>296840</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16160</td><td>N. PARACHUTE EF07D-29 F29 59</td><td>RI</td></tr> <tr><td>296841</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16161</td><td>N. PARACHUTE EF03B-32 F29 59</td><td>RI</td></tr> <tr><td>296842</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16162</td><td>N. PARACHUTE EF15A-29 F29 59</td><td>RI</td></tr> <tr><td>296843</td><td>WELL</td><td>AL</td><td>02/04/2013</td><td>LO</td><td>045-16163</td><td>N. PARACHUTE EF15B-29 F29 59</td><td>RI</td></tr> <tr><td>296844</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16164</td><td>N. PARACHUTE EF12C-29 F29 59</td><td>RI</td></tr> <tr><td>296845</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16165</td><td>N. PARACHUTE EF12A-29 F29 59</td><td>RI</td></tr> <tr><td>296846</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16166</td><td>N. PARACHUTE EF10B-29 F29 59</td><td>RI</td></tr> <tr><td>296847</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16167</td><td>N. PARACHUTE EF11B-29 F29 59</td><td>RI</td></tr> <tr><td>296848</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16168</td><td>N. PARACHUTE EF11D-29 F29 59</td><td>RI</td></tr> <tr><td>296849</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16169</td><td>N. PARACHUTE EF11A-29 F29 59</td><td>RI</td></tr> <tr><td>296850</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16170</td><td>N. PARACHUTE EF14A-29 F29 59</td><td>RI</td></tr> <tr><td>296851</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16171</td><td>N. PARACHUTE EF14B-29 F29 59</td><td>RI</td></tr> <tr><td>296852</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16172</td><td>N. PARACHUTE EF14C-29 F29 59</td><td>RI</td></tr> <tr><td>296853</td><td>WELL</td><td>AL</td><td>10/13/2011</td><td>LO</td><td>045-16173</td><td>N. PARACHUTE EF03A-32 F29 59</td><td>RI</td></tr> </tbody> </table>								Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	296840	WELL	AL	10/13/2011	LO	045-16160	N. PARACHUTE EF07D-29 F29 59	RI	296841	WELL	AL	10/13/2011	LO	045-16161	N. PARACHUTE EF03B-32 F29 59	RI	296842	WELL	AL	10/13/2011	LO	045-16162	N. PARACHUTE EF15A-29 F29 59	RI	296843	WELL	AL	02/04/2013	LO	045-16163	N. PARACHUTE EF15B-29 F29 59	RI	296844	WELL	AL	10/13/2011	LO	045-16164	N. PARACHUTE EF12C-29 F29 59	RI	296845	WELL	AL	10/13/2011	LO	045-16165	N. PARACHUTE EF12A-29 F29 59	RI	296846	WELL	AL	10/13/2011	LO	045-16166	N. PARACHUTE EF10B-29 F29 59	RI	296847	WELL	AL	10/13/2011	LO	045-16167	N. PARACHUTE EF11B-29 F29 59	RI	296848	WELL	AL	10/13/2011	LO	045-16168	N. PARACHUTE EF11D-29 F29 59	RI	296849	WELL	AL	10/13/2011	LO	045-16169	N. PARACHUTE EF11A-29 F29 59	RI	296850	WELL	AL	10/13/2011	LO	045-16170	N. PARACHUTE EF14A-29 F29 59	RI	296851	WELL	AL	10/13/2011	LO	045-16171	N. PARACHUTE EF14B-29 F29 59	RI	296852	WELL	AL	10/13/2011	LO	045-16172	N. PARACHUTE EF14C-29 F29 59	RI	296853	WELL	AL	10/13/2011	LO	045-16173	N. PARACHUTE EF03A-32 F29 59	RI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																								
296840	WELL	AL	10/13/2011	LO	045-16160	N. PARACHUTE EF07D-29 F29 59	RI																																																																																																																								
296841	WELL	AL	10/13/2011	LO	045-16161	N. PARACHUTE EF03B-32 F29 59	RI																																																																																																																								
296842	WELL	AL	10/13/2011	LO	045-16162	N. PARACHUTE EF15A-29 F29 59	RI																																																																																																																								
296843	WELL	AL	02/04/2013	LO	045-16163	N. PARACHUTE EF15B-29 F29 59	RI																																																																																																																								
296844	WELL	AL	10/13/2011	LO	045-16164	N. PARACHUTE EF12C-29 F29 59	RI																																																																																																																								
296845	WELL	AL	10/13/2011	LO	045-16165	N. PARACHUTE EF12A-29 F29 59	RI																																																																																																																								
296846	WELL	AL	10/13/2011	LO	045-16166	N. PARACHUTE EF10B-29 F29 59	RI																																																																																																																								
296847	WELL	AL	10/13/2011	LO	045-16167	N. PARACHUTE EF11B-29 F29 59	RI																																																																																																																								
296848	WELL	AL	10/13/2011	LO	045-16168	N. PARACHUTE EF11D-29 F29 59	RI																																																																																																																								
296849	WELL	AL	10/13/2011	LO	045-16169	N. PARACHUTE EF11A-29 F29 59	RI																																																																																																																								
296850	WELL	AL	10/13/2011	LO	045-16170	N. PARACHUTE EF14A-29 F29 59	RI																																																																																																																								
296851	WELL	AL	10/13/2011	LO	045-16171	N. PARACHUTE EF14B-29 F29 59	RI																																																																																																																								
296852	WELL	AL	10/13/2011	LO	045-16172	N. PARACHUTE EF14C-29 F29 59	RI																																																																																																																								
296853	WELL	AL	10/13/2011	LO	045-16173	N. PARACHUTE EF03A-32 F29 59	RI																																																																																																																								

296854	WELL	AL	10/13/2011	LO	045-16174	N. PARACHUTE EF02A-32 F29 59	RI
296855	WELL	AL	10/13/2011	LO	045-16175	N. PARACHUTE EF03C-32 F29 59	RI

General Comment:

This is a Final Reclamation Inspection for Loc#335963 The Variance Request, Doc# 401590990 was Approved 10/25/18 with COA:

Caerus will maintain the un-reclaimed location and access road in a weed free condition and without stormwater issues until it has passed a final reclamation inspection.

Location is a County Permitted Laydown & Storage Yard

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____ Pass _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Pass _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Final Approved Land use as Laydown Storage Yard make most of the above Pass/Fail Tabs NA. This Inspection confirmed stabilization of site and that NO Stormwater, Erosion or Weed concerns were evident. Refer to Photos Attached.

Corrective Action: _____ Date _____

Overall Final Reclamation	Pass	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>
---------------------------	------	---------------------------------	--------------------------	---------------------	--------------------------

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692400318	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4641252