

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 1

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 2

View north at former separator foundation slab



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 3

Excavation east of former separator foundation concrete slab

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 4

Soil stockpile near separator foundation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 5

Soil stockpile near separator foundation



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 6

Former berm gravel stockpile



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 7

View west-northwest along northern edge of former tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 8

View west-northwest along southern edge of former tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 9

View south across former tank battery eastern berm toward former produced water pit area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Timka Resources LTD – North Minto J Sand Battery
Inspection Date: 11/01/2018



Photo # - 10

View northwest toward former separator area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources