

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302343**



Location Photo #1



Location Photo #2

Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302343



Location Photo #3, Unmarked flow lines



Location Photo #4, Unmarked flow line

Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302343



Location Photo #5, Sediment migration onto location from cut slope.



Location Photo #6, Sediment migration onto location from cut slope.

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302343**



Location Photo #7, Sediment migration onto location from cut slope.



Location Photo #8, Sediment migration onto location from cut slope.

**Inspection Photo
Clough RWF 43-15
API # 045-11180
Inspection # 689302343**



Location Photo #9, Sediment migration onto location from cut slope.