

Final Reclamation Inspection

November 9, 2018

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-09795

Inspection Document #: 682404177

Weld County, CO

SESE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: VALARIE G. HITCHINGS #1

API: 05-123-09795



Photo 1. Photo taken from the location on September 5, 2018. Photo illustrates the Operator failed to remove debris after previous corrective actions were issued.



Photo 2. Photo taken from the location on September 5, 2018. Photo illustrates the Operator failed to remove equipment after previous corrective actions were issued.

Inspection Photos

Location Name: VALARIE G. HITCHINGS #1

API: 05-123-09795



Photo 3. Photo taken from the location on November 9, 2018. No equipment or debris was observed at the previous location. Appears the Operator has removed equipment per the previous corrective action.