

Final Reclamation Inspection

November 9, 2018

Operator: TOP OPERATING COMPANY - 39560

API: 05-123-08139

Inspection Document #: 682404179

Weld County, CO

NENE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 1. Photo taken from the eastern battery location on September 5, 2018. Photo illustrates the Operator failed to remove equipment after previous corrective actions were issued.



Photo 2. Photo taken from the eastern battery location on November 9, 2018. Photo illustrates the Operator is in process of removing equipment. Operator shall remove all equipment by February 28, 2019.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 3. Photo taken from the battery location on September 5, 2018, facing South. Photo illustrates noxious thistles and undesirable weeds (Kochia and Russian thistle) were observed throughout the entire battery location.



Photo 4. Photo taken from the battery location on November 9, 2018, facing South. Operator has mowed the entire battery location. Appears viable noxious thistle rosettes were still observed throughout portions of the battery location.

Inspection Photos
Location Name: SCHNEIDER #1
API: 05-123-08139



Photo 5. Photo taken from the battery location on November 9, 2018. Photo illustrates a viable Musk thistle rosette, a List B Colorado noxious weed. Operator shall continue to control and manage weeds and erosion until the Location has 2 consecutive growing seasons with no noxious weeds.