

## Inspection Photos

Location Name: MOORE 4-11 MH

Location ID: 05-103-09064

Inspection: 679701689



Photo 1. Location looking southwest.



Photo 2. Tank without NFPA label.



**Inspection Photos**  
**Location Name: MOORE 4-11 MH**  
**Location ID: 05-103-09064**  
**Inspection: 679701689**



**Photo 3. Unused barrels on next to pump jack.**



**Photo 4. Container without secondary containment.**

## Inspection Photos

Location Name: MOORE 4-11 MH

Location ID: 05-103-09064

Inspection: 679701689



**Photo 5. Pit next to tank.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources