

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2018

Submitted Date:

11/08/2018

Document Number:

692600716**FIELD INSPECTION FORM**
 Loc ID 314220 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10227Name of Operator: CHOLLA PETROLEUM INCAddress: 6688 N CENTRAL EXPRESSWAY 1610City: DALLAS State: TX Zip: 75206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone          | Email                  | Comment |
|---------------|----------------|------------------------|---------|
| Cahill, Terry | (214) 692-7052 | tcahill@chollapetr.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 285481      | WELL | PR     | 06/30/2006  | GW         | 099-06890 | DUKE 1-18     | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                                     |       |  |
|--------------------|-------------------------------------|-------|--|
| <b>Lease Road:</b> |                                     |       |  |
| Type               | Access                              |       |  |
| comment:           | Dirt road along edge of farm ground |       |  |
| Corrective Action  |                                     | Date: |  |

Overall Good: ☒

|                      |                           |       |  |
|----------------------|---------------------------|-------|--|
| <b>Signs/Marker:</b> |                           |       |  |
| Type                 | WELLHEAD                  |       |  |
| Comment:             | Lease sign mounted to HGS |       |  |
| Corrective Action:   |                           | Date: |  |
| Type                 | TANK LABELS/PLACARDS      |       |  |
| Comment:             | Stickers on tank          |       |  |
| Corrective Action:   |                           | Date: |  |

|                           |       |  |  |
|---------------------------|-------|--|--|
| Emergency Contact Number: |       |  |  |
| Comment:                  |       |  |  |
| Corrective Action:        |       |  |  |
|                           | Date: |  |  |

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                                   |                                  |       |                 |
|-----------------------------------|----------------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                                  |       | corrective date |
| Type: Horizontal Heated Separator | # 1                              |       |                 |
| Comment:                          |                                  |       |                 |
| Corrective Action:                |                                  | Date: |                 |
| Type: Ancillary equipment         | # 1                              |       |                 |
| Comment:                          | Solar powered cathodic rectifier |       |                 |
| Corrective Action:                |                                  | Date: |                 |
| Type: Gas Meter Run               | # 1                              |       |                 |
| Comment:                          |                                  |       |                 |
| Corrective Action:                |                                  | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type           | Tank ID | SE GPS                |
|--------------------|---|----------|----------------|---------|-----------------------|
| PRODUCED WATER     | 1 | 200 BBLS | FIBERGLASS AST |         | 38.219220,-102.630200 |
| Comment:           |   |          |                |         |                       |
| Corrective Action: |   |          |                |         | Date:                 |

**Paint**

|           |  |
|-----------|--|
| Condition |  |
|-----------|--|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

| Inspected Facilities |           |       |      |             |           |         |    |               |    |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 285481    | Type: | WELL | API Number: | 099-06890 | Status: | PR | Insp. Status: | PR |
| Producing Well       |           |       |      |             |           |         |    |               |    |
| Comment:             | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:   |           |       |      | Date:       |           |         |    |               |    |

Reclamation - Storm Water - Pit

Storm Water:

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Location is farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT