

## Inspection Photos

Location Name: Hungenberg-66N65W /33SWNE

Location #: 323570



### Photo #1

**Hungenberg 7-33 (API # 05-123-13211) wellsite**

**Appears to be P&A'd**

**Wellhead has NOT been cut & capped.**



## Inspection Photos

Location Name: Hungenberg-66N65W /33SWNE

Location #: 323570



### Photo #2

Hungenberg 7-33 (API # 05-123-13211) Tank Battery  
Site

P&A'd

All Equipment Removed

