

# *Inspection Photos*

*Loc#335013*

*Operator: Caerus*

*Inspection Number: 692400326*

*Inspection Date: 10/25/2018*





Photo#1:  
Overview of Location from entry to South

October 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Riley Loc#335013



Photo#2:  
View of Interim Reclamation area & Marked Anchors.

October 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Riley Loc#335013



Photo#3:  
Containers stored at East side of separator facility.

October 25, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus Riley Loc#335013



Photo#4:  
Unmarked Anchor.

October 25, 2018



Photo#5:  
Houndstongue rosette

