

Final Reclamation Inspection

November 9, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-20854

Inspection Document #: 682404181

Weld County, CO

SWSE Section 25 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HEIN #15-25A
API: 05-123-20854




Photo 1. Photo taken east of the location, facing West. Photo illustrates a land use change to mining development. Two wells by two different operators have been plugged and abandoned. No visual evidence of oil and gas equipment at the Location.