

Inspection Photos

Operator: Petrox Resources

API: 05-007-06215

Date: 11/06/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward.



Photo 3. View of the southern project area from the southwestern corner facing eastward. Project area is infested with musk thistles (*Carduus nutans*) and Canada thistles (*Cirsium arvense*).



Photo 4. View of the northern project area from the northwestern corner facing eastward. Canada thistles are yellow thistles across the cut-slope.



Photo 5. Birdseye view of Canada thistles infested within the project area.