

Inspection Photos

API#057-06487

Operator: Laramie

Inspection Number: 692400340

Inspection Date: 10/30/2018





Photo#1:
Overview of Location from entry to Northwest.

October 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Fugua PA API#057-06487



Photo#2:
Overview of Location to Southeast.

October 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Fugua PA API#057-06487



Photo#3:

Close up of crimped in & assumed seeded surface. Green emerged rosettes were identified as Canada thistle; indicating need for ongoing Weed monitoring & control Program.

October 30, 2018



Photo#4:
Remaining Perimeter ditches showing lack of complete re-contouring.

October 30, 2018



Photo#5:
Refer to Description in Photo#4.





Photo#6:
Access road leading out of Location, view to Southeast.

October 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Fugua PA API#057-06487



Photo#7:
Views of un-reclaimed access road.

Photo#8:
Refer to description in Photo#7.

October 30, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Fugua PA API#057-06487