

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2018

Submitted Date:

11/07/2018

Document Number:

689702045**FIELD INSPECTION FORM**
 Loc ID 383337 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**22 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277264	WELL	PR	09/04/2013	GW	045-10653	CASCADE CREEK 608-43-31	PR
302009	WELL	PR	08/14/2011	GW	045-18345	Cascade Creek 697-09-25A	PR
302012	WELL	PR	08/07/2011	GW	045-18348	Cascade Creek 697-08-47B	PR
302013	WELL	PR	08/19/2014	GW	045-18349	Cascade Creek 697-08-47A	PR
302014	WELL	PR	09/08/2011	GW	045-18350	Cascade Creek 697-08-39	PR
302015	WELL	PR	08/19/2014	GW	045-18351	Cascade Creek 697-08-31B	PR
302016	WELL	PR	09/08/2011	GW	045-18352	Cascade Creek 697-08-31A	PR
302017	WELL	PR	02/22/2016	GW	045-18353	Cascade Creek 697-08-23B	PR
302018	WELL	PR	08/13/2013	GW	045-18354	Cascade Creek 697-09-25B	PR
419502	WELL	PR	09/12/2011	GW	045-19936	Cascade Creek 697-08-29A	PR
419504	WELL	PR	09/09/2011	GW	045-19937	Cascade Creek 697-08-21	PR
419505	WELL	PR	09/08/2011	GW	045-19938	Cascade Creek 697-08-37B	PR
419507	WELL	PR	09/08/2011	GW	045-19939	Cascade Creek 697-08-45	PR
419509	WELL	PR	09/08/2011	GW	045-19940	Cascade Creek 697-08-37A	PR
419510	WELL	PR	09/08/2011	GW	045-19941	Cascade Creek 697-08-46B	PR
419511	WELL	PR	09/09/2011	GW	045-19942	Cascade Creek 697-08-20	PR
419516	WELL	PR	09/12/2011	GW	045-19943	Cascade Creek 697-08-29B	PR
419517	WELL	PR	10/03/2011	GW	045-19944	Cascade Creek 697-08-29C	PR

General Comment:

Routine FIU General Field Inspection

--

Location**Lease Road:**

Type			
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	The phone number for local emergency services (911 where available) and the public road used to access the site is not posted on battery sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/08/2018

Emergency Contact Number:

Comment:	970-285-0497	
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	277264	Type:	WELL	API Number:	045-10653	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302009	Type:	WELL	API Number:	045-18345	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302012	Type:	WELL	API Number:	045-18348	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302013	Type:	WELL	API Number:	045-18349	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302014	Type:	WELL	API Number:	045-18350	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302015	Type:	WELL	API Number:	045-18351	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302016	Type:	WELL	API Number:	045-18352	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	302017	Type:	WELL	API Number:	045-18353	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID:	302018	Type:	WELL	API Number:	045-18354	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419502	Type:	WELL	API Number:	045-19936	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419504	Type:	WELL	API Number:	045-19937	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419505	Type:	WELL	API Number:	045-19938	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419507	Type:	WELL	API Number:	045-19939	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419509	Type:	WELL	API Number:	045-19940	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419510	Type:	WELL	API Number:	045-19941	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	419511	Type:	WELL	API Number:	045-19942	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	419516	Type:	WELL	API Number:	045-19943	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	419517	Type:	WELL	API Number:	045-19944	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
		Compaction	Pass			
		Gravel	Pass			
		Culverts	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401831447	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638656
689702046	Inspection 689702045 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4638651