

Inspection Photos
Location Name: Kreykes 13-11
API# 123-23683



Open top tanks (facing east)



Open top tanks (facing west)

Inspection Photos
Location Name: Kreykes 13-11
API# 123-23683



Grounding rod on south tank



Grounding rod on north tank



Inspection Photos
Location Name: Kreykes 13-11
API# 123-23683



Colorado Oil & Gas Conservation Commission
40.49249, -104.835, 1469.0m, 358°
11/13/2018 15:55:22

Wellhead



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources