

Inspection Photos
Location Name: Grizzly 0881 2-1H36
API: 05-057-06593

17
State of Colorado
Oil and Gas Conservation Commission
15100 Lincoln Street, Suite 800, Denver, Colorado 80202-3288 FAX: (303) 839-2109

BRADENHEAD TEST REPORT

1. Name of Operator: Grizzly 0881 2-1H36
2. Well Name: Grizzly 0881 2-1H36
3. Location (County, Sec, Twp, Range): El Paso Co., 36S, 10E, 12N
4. Date of Test: 11/13/18
5. Test Type: Pressure Buildup
6. Test Results: See attached sheets

STEP 2: BRADENHEAD TEST

7. Test Results (Pressure, Time, etc.):
8. Test Results (Pressure, Time, etc.):
9. Test Results (Pressure, Time, etc.):

STEP 3: INTERMEDIATE CHOKING TEST

10. Test Results (Pressure, Time, etc.):
11. Test Results (Pressure, Time, etc.):
12. Test Results (Pressure, Time, etc.):

13. Signature: [Signature]
14. Date: 11/13/18

Photo 1. Photo of Form 17 as filled out and signed in the field.



Photo 2. Bad housekeeping. Oily bucket actively dripping. Miscellaneous parts.