

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #1

70 Ranch 5-63-22-58H (API # 05-123-35773) wellsite

Unused Pumpjack

from previous FIR



Photo #2

70 Ranch 5-63-22-58H wellsite

Unused Pumpjack



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #3

70 Ranch 5-63-22-58H Tank Battery

from previous FIR



Photo #4

70 Ranch 5-63-22-58H Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #5

70 Ranch 5-63-22-58H Crude tanks

Soil stain

From previous FIR



Photo #6

70 Ranch 5-63-22-58H Crude tanks

Soil Stain



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #7

70 Ranch 5-63-22-58H Separator Berms

Rodent burrow – Compromised berms

From previous FIR



Photo #8

70 Ranch 5-63-22-58H Separator Berms

Burrows appear to be mitigated

Berm integrity intact



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #9

70 Ranch 5-63-22-58H Wellsite

Soil stain

From previous FIR



Photo #10

70 Ranch 5-63-22-58H Wellsite

Soil stain appears to be mitigated



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Colorado Oil & Gas Conservation Commission
40.39187, -104.41541, 1402.0m, 36°
2018/11/13 04:05:07 PM

Photo #11

70 Ranch 5-63-22-58H Crude tank berm floor

Oily waste - rags



Colorado Oil & Gas Conservation Commission
40.39181, -104.41528, 1399.0m, 333°
2018/11/13 03:06:57 PM

Photo #12

70 Ranch 5-63-22-58H Battery

Condensate sumps – Capacity unknown



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #13

70 Ranch 5-63-22-58H Gas Meter Run

View 1

**Apparent methanol tank NOT labeled
No placards**



Photo #14

70 Ranch 5-63-22-58H Gas Meter Run

View 2

**Apparent methanol tank NOT labeled
No placards**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 70 Ranch Pad /5-63-22-58H

Location #: 429258



Photo #15

70 Ranch 5-63-22-58H Compressor

View 1

Fire Damage from incident on 11/10/2018



Photo #16

70 Ranch 5-63-22-58H Compressor

View 2

Fire Damage from incident on 11/10/2018

