

# *Inspection Photos*

*Loc#451456*

*Operator: Sandridge*

*Inspection Number: 692400347*

*Inspection Date: 10/30/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to East.

October 30 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Refuge Loc#451456



Photo#2:

View along South Berm; emerged cool season vegetation is visible.

October 30 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Refuge Loc#451456



Photo#3:  
Culverts have been installed along access road..

October 30 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Refuge Loc#451456



Photo#4:  
Wattles have become Debris.

October 30 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Refuge Loc#451456