

Inspection Photos

Location Name: SAGEBRUSH HILLS 4502

Location ID: 05-103-08082

Inspection: 679701715



Photo 1. Location looking southeast.



Photo 2. Unused upside down open top tank on location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SAGEBRUSH HILLS 4502

Location ID: 05-103-08082

Inspection: 679701715



Photo 3. Riser not capped or lock out tagged out.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources