

Inspection Photos
Location Name: FEDERAL 1-17
Location ID: 05-103-07897
Inspection: 679701701



Photo 1. Location looking southeast



Photo 2. Pump jack is partially disassembled.

Inspection Photos
Location Name: FEDERAL 1-17
Location ID: 05-103-07897
Inspection: 679701701



Photo 3. Weeds in pit



Photo 4. Weeds on tank battery berm and inside berm parameter

Inspection Photos
Location Name: FEDERAL 1-17
Location ID: 05-103-07897
Inspection: 679701701



Photo 5. Oily waste from tank valve.



Photo 6. Oily waste on ground near wellhead

Inspection Photos
Location Name: FEDERAL 1-17
Location ID: 05-103-07897
Inspection: 679701701



Photo 7. Unused empty barrels



Photo 8. Riser not capped or locked out tagged out