

Inspection Photos

11/14/2018

Operator: MAGPIE OPERATING, INC - 52530

Location ID: 319898

Inspection Doc. Number: 682504148

Adams County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 319898



Photo 1: Photo from the well, facing south.



Photo 2: Photo from the east end of the location, facing south. Photos 2-4 provide overview of the location. Adjacent reference area cropland.

Inspection Photos
Operator: MAGPIE OPERATING, INC - 52530
Location ID: 319898



Photo 3: Photo from the east end of the location, facing west. Photos 2-4 provide overview of the location. Adjacent reference area cropland.



Photo 4: Photo from the east end of the location, facing north. Photos 2-4 provide overview of the location. Adjacent reference area cropland.