

Final Reclamation Inspection

November 14, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-11909

Inspection Document #: 682404212

Weld County, CO

SWSW Section 5 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ROUKEMA #5-1
API: 05-123-11909



Photo 1. Photo taken from the entrance of the well location access road, facing North. No equipment was observed at the Location. Location will remain in process, as this location does not meet Rule 1004 standards and is not reflective of reference area vegetative levels.



Photo 2. Photo taken from the well location, facing South. See comments under Photo 1.

Inspection Photos
Location Name: ROUKEMA #5-1
API: 05-123-11909



Photo 3. Photo taken along a portion of the well access road, facing South. See comments under Photo 1.



Photo 4. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: ROUKEMA #5-1
API: 05-123-11909



Photo 5. Photo taken from the eastern tank battery location, facing East. Little, to no, vegetation establishment was observed.



Photo 6. Photo taken from the western tank battery location, facing West. See comments under Photo 5.