




Photo of produced water line block valve and fittings (valve can removed) taken by BP personnel.



Photo of produced water transfer line fitting/ elbow (at valve can removed) taken by BP personnel.



Inspection work on 6" PW transfer line being completed by BP personnel.