

Inspection Photos
Location Name: VICTOR USX W 23-4
Location ID: 319386



Colorado Oil & Gas Conservation Commission
40.10382, -104.76321, 145°
2018/11/16 09:31:54

PHOTO 1: WELLHEAD



Colorado Oil & Gas Conservation Commission
40.12891, -104.75041, 1552.0m, 137°
2018/11/16 09:31:04

PHOTO 2: TANK BATTERY