

Inspection Photos
Location Name: JOHN A. KUNZMAN 4
Location ID: 311327



PHOTO 1: WELLHEAD



PHOTO 2: VALVE & BULLPLUG LEAKING

Inspection Photos
Location Name: JOHN A. KUNZMAN 4
Location ID: 311327



PHOTO 3: STAINED SOIL UNDER VALVE & AROUND WH



PHOTO 4: PLUNGER ROD PACKING LEAKING

Inspection Photos
Location Name: JOHN A. KUNZMAN 4
Location ID: 311327




PHOTO 5: WH PACKING LEAKING




PHOTO 6: STAINED SOIL