

**Inspection Photos**  
**Location Name: PARKER 2**  
**Location ID: 333125**



**PHOTO 1: PARKER 2 WELLHEAD**



**PHOTO 2: BANGERT 34-19 WELLHEAD**

**Inspection Photos**  
**Location Name: PARKER 2**  
**Location ID: 333125**



**PHOTO 3: STAINED SOIL AROUND WELLHEAD**

**PHOTO 4: STAINED SOIL UNDER GEARBOX ON PUMPING UNIT**

**Inspection Photos**  
**Location Name: PARKER 2**  
**Location ID: 333125**



**PHOTO 5: STAINED SOIL AROUND PRIME MOVER & INSIDE SKID.**

**PHOTO 6: STAINED SOIL NEAR PRIME MOVER MUFFLER SKID.**