

Inspection Photos

Location Name: M.V. SMITH 35-2

Location ID: 05-103-05377

Inspection: 679701725



Photo 1. Location looking northwest.



Photo 2. Oily waste around wellhead.



Inspection Photos
Location Name: M.V. SMITH 35-2
Location ID: 05-103-05377
Inspection: 679701725



Photo 3. Weeds on and inside berm.



Photo 4. Weeds around pump jack.

Inspection Photos
Location Name: M.V. SMITH 35-2
Location ID: 05-103-05377
Inspection: 679701725



Photo 5. Unmarked deadman.



Photo 6. Berm capacity insufficient.