

Inspection Photos
Location Name: M.V. SMITH 31
Location ID: 05-103-05344
Inspection: 679701729



Photo 1. Location looking north.



Photo 2. Location looking north. Weeds inside berm area.

Inspection Photos
Location Name: M.V. SMITH 31
Location ID: 05-103-05344
Inspection: 679701729



Photo 3. No signage on tank.



Photo 4. Weeds on berm.

Inspection Photos

Location Name: M.V. SMITH 31

Location ID: 05-103-05344

Inspection: 679701729



Photo 5. Unmarked deadman.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources