

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/16/2018

Submitted Date:

11/16/2018

Document Number:

692600797

**FIELD INSPECTION FORM**

Loc ID 304028 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253956      | WELL | PR     | 10/21/2007  | GW         | 125-07834 | GODSEY 44-20  | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                           |  |       |
|--------------------|---------------------------|--|-------|
| <b>Lease Road:</b> |                           |  |       |
| Type               | Access                    |  |       |
| comment:           | Two track through pasture |  |       |
| Corrective ActionL |                           |  | Date: |

Overall Good:

|                      |                    |  |       |
|----------------------|--------------------|--|-------|
| <b>Signs/Marker:</b> |                    |  |       |
| Type                 | WELLHEAD           |  |       |
| Comment:             | Lease sign by unit |  |       |
| Corrective Action:   |                    |  | Date: |

|                                  |   |  |             |
|----------------------------------|---|--|-------------|
| <b>Emergency Contact Number:</b> |   |  |             |
| Comment:                         | <input style="width: 100%;" type="text"/> |  |             |
| Corrective Action:               | <input style="width: 100%;" type="text"/> |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |   |  |       |
|--------------------|---|--|-------|
| <b>Fencing/:</b>   |   |  |       |
| Type               | PUMP JACK   |  |       |
| Comment:           | Metal panels around unit, wellhead and meter shed |  |       |
| Corrective Action: |   |  | Date: |

|                           |  |  |                 |
|---------------------------|--|--|-----------------|
| <b>Equipment:</b>         |  |  | corrective date |
| Type: Gas Meter Run       | # 1                                    |  |                 |
| Comment:                  | Meter run in metal shed                |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Ancillary equipment | # 2                                    |  |                 |
| Comment:                  | Electric panel and telemetry equipment |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Prime Mover         | # 1                                    |  |                 |
| Comment:                  | Electric motor                         |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Pump Jack           | # 1                                    |  |                 |
| Comment:                  | Jensen unit                            |  |                 |
| Corrective Action:        |  |  | Date:           |
| Type: Vertical Separator  | # 1                                    |  |                 |
| Comment:                  | Vertical gas separator in metal shed   |  |                 |
| Corrective Action:        |  |  | Date:           |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 253956 Type: WELL API Number: 125-07834 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Compaction              | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT