

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401798198
Date Received:
10/18/2018

FIR RESOLUTION FORM

CA Summary:
1 of 2 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 95960
Name of Operator: WEXPRO COMPANY
Address: P O BOX 45003
City: SALT LAKE CITY State: UT Zip: 84145-0601
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
April Stegall 307-352-7561 april.stegall@dominionenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 692400180
Inspection Date: 09/26/2018 FIR Submit Date: 10/03/2018 FIR Status:

Inspected Operator Information:

Company Name: WEXPRO COMPANY Company Number: 95960
Address: P O BOX 45003
City: SALT LAKE CITY State: UT Zip: 84145-0601

LOCATION - Location ID: 312853

Location Name: STATE OF COLORADO-611N97W Number: 16NENE County: MOFFAT
Qtrqtr: NENE Sec: 16 Twp: 11N Range: 97W Meridian: 6
Latitude: 40.918520 Longitude: -108.289890

FACILITY - API Number: 05-081-00 Facility ID: 222613

Facility Name: STATE OF COLORADO Number: 1
Qtrqtr: NENE Sec: 16 Twp: 11N Range: 97W Meridian: 6
Latitude: 40.918520 Longitude: -108.289890

CORRECTIVE ACTIIONS:

2 CA# 119264

Corrective Action: Comment repeated here as appeared to be being cut off in Comment Box:
Form 27 Doc#2315410 was submitted 9/3/15. No further results or reports of activity have been submitted. The Pit Not being Closed is delaying Final Reclamation of the Location which is now more than 2 years past due date for Reclamation activities to be completed.
CA) Contact COGCC EPS, Kris Neidel to update & report on any soil analysis results & status/progress of Remediation Workplan.

Date: 10/17/2018

Response: CA COMPLETED

Date of Completion: 10/16/2018

Operator Comment: Please see the attachments regarding CA #2.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Though Operator has complied with above CA; Wexpro needs to Submit Analysis & Remediation plan ASAP. Reclamation can not keep being delayed because Operator cannot "come up with a Remediation Plan". Follow up Inspection will be conducted.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments regarding CA #2.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: April Stegall

Signed: _____

Title: Reclamation Agent

Date: 10/18/2018 8:15:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401798198	FIR RESOLUTION SUBMITTED
401798291	Form 27
401798292	Email to COGCC, Kris Neidel
401800892	Email to COGCC, Lou Colby

Total Attach: 4 Files