

**Inspection Photo
Bennet 33-5
API # 045-07254
Inspection # 689302374**



Location Photo #1



**Location Photo #2, Hole in berm south
end of separators.**