

**Inspection Photo
Boulton 33-6A
API # 045-07927
Inspection # 689302376**



Location Photo #1



**Location Photo #2, Sediment being moved
off location.**

**Inspection Photo
Boulton 33-6A
API # 045-07927
Inspection # 689302376**



Location Photo #3, Sediment being moved off location.



Location Photo #4, Sediment being moved off location.