

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Spill/Release Point ID #458834 source.



Pipeline ROW where release occurred.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Incised channel on hillside along flow path.



Flow path towards irrigation ditch.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Flow path towards irrigation ditch. Incised channel can be seen in top center of photo.



North Point of Contact with Citizen's Ditch.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Absorbent boom below Point of Contact with irrigation ditch.



Flow path of release with irrigation ditch in the foreground.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Citizen's Animas Ditch upstream of Kitt's property.



Citizen's Animas Ditch near inlet for High Flume Canyon siphon.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



High Flume Canyon siphon bypass on irrigation ditch.



Water bypassing siphon through Kitt's property.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Head gate for pond #4 (Christine's Pond).



Inlet to Christine's Pond with absorbent booms in place.



Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Booms along High Flume Canyon siphon bypass.



Boom along irrigation ditch near Kitt's residence.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Box culvert in High Flume Canyon under CR 213.



Photo of High Flume Canyon upstream of box culvert under CR 213.

Inspection Photos
Location Name: Thomas Jacquez E #1 PW Line
Spill/Release Point ID #458834



Ponds #1-3.



Ponds #4-5.