

Inspection Photos

Location Name: WEST DRAGON TRAIL 4-32-2-2

Location ID: 05-103-09648

Inspection: 679701796



Photo 1. Location looking north.



Photo 2. Blow down pit without permit on file.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources