

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2018

Submitted Date:

11/13/2018

Document Number:

692600776**FIELD INSPECTION FORM**

Loc ID 413318 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10330Name of Operator: INVESTMENT EQUIPMENT LLCAddress: 412 W PLATTE AVECity: FT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Chisolm, Jim	405-642-9437	investmentequipment@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413316	WELL	SI	01/01/2017	OW	061-06838	TRADE WINDS 1-28	SI

General Comment:

Initial MIT

Location

Lease Road:			
Type	Access		
comment:	Gravel entrance off of HWY 96		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by entrance		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	413316	Type:	WELL	API Number:	061-06838	Status:	SI	Insp. Status:	SI
Producing Well									
Comment:	WELL IS SI AT TIME OF INSPECTION. MIRU PROSTIM. LOAD CSG W/1BBL. PRESSURED UP TO 480 PSI. 5 MIN 450#. 10 MIN 440#. 15 MIN 440#. LOSS OF 40 PSI								
Corrective Action:								Date:	

--	--	--	--	--	--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692600778	Form 21	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4645584