

Inspection Photos
Location Name: Rhodes #1
API: 05-067-09955



Rhodes #1 location photo.



Stained gravel near pump jack exhaust.

Inspection Photos
Location Name: Rhodes #1
API: 05-067-09955



Rhodes #1 pump jack and well head.



Well head, pump jack, and surrounding gravel are stained and wet.

Inspection Photos
Location Name: Rhodes #1
API: 05-067-09955



Well head and surrounding gravel are stained and wet.



PA marker for State Gas Com MZ-1