

**Inspection Photos**  
**Location Name: Nate Springs 1**  
**Location ID: 05-103-09383**  
**Inspection: 679701824**



**Photo 1. Location looking northeast.**



**Photo 2. Wellhead. Not venting. No valve below cellar. Valve above cellar closed.**