

Final Reclamation Inspection

November 14, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-25003

Inspection Document #: 682404216

Weld County, CO

NWSW Section 5 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WILMOTH C #5-20
API: 05-123-25003



Photo 1. Photo taken from the offsite tank battery, facing North. Well was plugged and abandoned on 01/24/2017; this appears to be the last well plugged that used this offsite tank battery. Operator shall comply with Rule 1004 standards to remove all equipment and perform final reclamation activities. Another nearby PA location used this battery and already has a corrective action date- see FIR Doc. #682504032.

Inspection Photos
Location Name: WILMOTH C #5-20
API: 05-123-25003



Photo 2. Close-up photo of the meter shed left at the tank battery, facing South.

Inspection Photos
Location Name: WILMOTH C #5-20
API: 05-123-25003



Photo 3. Photo taken north of the well location, facing South along the former access road. There was a lock gate with livestock so Staff did not proceed to the well location. Staff will conduct a follow-up inspection once the equipment has been removed from the tank battery and the location meets Rule 1004 vegetative standards.

Inspection Photos
Location Name: WILMOTH C #5-20
API: 05-123-25003



Photo 4. Photo taken from the previous photo location, facing West. Photo illustrates the former access road.