

Final Reclamation Inspection

November 14, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-11796

Inspection Document #: 682404218

Weld County, CO

NENW Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: COX #8-1
API: 05-123-11796




Photo 1. Photo taken on 6/21/2017 from the well location, facing South. Inspection noted vegetation did not appear uniform with reference areas.

Inspection Photos
Location Name: COX #8-1
API: 05-123-11796



Photo 2. Close-up photo of the well location taken on 11/14/2018, facing West. Well location is not in compliance with Rule 1004 vegetative standards. Little to no establishment of reference area vegetation was observed and gravel did not appear to be properly removed.

Inspection Photos
Location Name: COX #8-1
API: 05-123-11796



Photo 3. Photo taken from the well location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: COX #8-1
API: 05-123-11796



Photo 4. Photo taken from the well location. Photo illustrates the presence of gravel which was not observed in reference areas.

Inspection Photos
Location Name: COX #8-1
API: 05-123-11796



Photo 5. Reference photo taken south of the well location, facing South. Photo illustrates that the well location is not reflective of reference area vegetative levels.