

Inspection Photos

11/19/2018

Operator: RED HAWK PETROLEUM LLC - 10503

Location ID: 427144

Inspection Doc. Number: 682504187

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the location, facing east. Photo shows interim areas and overview of the location.



Photo 2: Photo taken from the west end of the location, facing southeast. Photo shows interim areas and overview of the location.



Photo 3: Photo taken from the west end of the location, facing west. Photo shows access road.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 427144



Photo 4: Photo taken from the south end of the location, facing south. Photo of tanks on location.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 427144



Photo 5: Photo of PR well.

Inspection Photos
Operator: RED HAWK PETROLEUM LLC - 10503
Location ID: 427144



Photo 6: Photo taken from the southeast end of the location, facing west. Photo shows interim areas and overview of the location.



Photo 7: Photo taken from the southeast end of the location, facing north. Photo shows interim areas and overview of the location.