

Inspection Photos

11/19/2018

Operator: MARKUS PRODUCTION, INC - 53790

Location ID: 327257

Inspection Doc. Number: 682504191

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road entrance at CR 86 (40.611055°, -104.020340°).

Inspection Photos
Operator: MARKUS PRODUCTION, INC - 53790
Location ID: 327257



Photo 2: Photo taken from the access road, north of the location, facing south. Photo of access road.



Photo 3: Photo taken from the South end of the location, facing north. Photo shows area of the well that is bare and exposed soil. Well PA 7/5/2017, at least 2 growing seasons have passed; unable to find germination and desirable perennial vegetative establishment at well site



Photo 4: Photo taken from the east end of the well site, facing west. Photo shows area of the well that is bare and exposed soil. Well PA 7/5/2017, at least 2 growing seasons have passed; unable to find germination and desirable perennial vegetative establishment at well site



Photo 5: Photo taken from the adjacent reference area. Photo shows vegetation on the reference. Well site is not reflective of the reference area.




Photo 6: Most recent available (2013) google earth aerial imagery. Photo shows area of the well on the location. Blue outline shows areas where the previous photos show desirable perennial vegetative establishment is not occurring